

CRITICAL QUALITY CONTROL

CRITICAL DIMENSION | MAJOR DIMENSION

MODIFICATION LIST

NO.	DESCRIPTION OF CHANGE	REASON OF CHANGE	ECO NO.	DATE	DESIGNED	APPROVED
1						
2						

NO.	PART NAME	PART NUMBER	QTY	MATERIAL	FINISHED	REMARK
13	SCREW_TT_PS_PH_M3X8_ZINC	[illegible]	4			
14	SCREW_TT_PS_PH_M3X8_ZINC	[illegible]	10			
15	SCREW_TT_PS_PH_M3X8_ZINC	[illegible]	8			
16		[illegible]	1			
17	pcb_cover_bottom_pr	[illegible]	1			
18	pcb_cover_top_pr	[illegible]	1			
19	pcb_cover_top_pr	[illegible]	1			
20	pcb_cover_top_pr	[illegible]	1			
21	pcb_cover_top_pr	[illegible]	1			
22	pcb_cover_top_pr	[illegible]	1			
23	cover_pcb_bottom	[illegible]	1			
24	ASSY COVER CABLE_UPPER	[illegible]	1			
25	ASSY COVER CABLE_UPPER	[illegible]	1			
26	ASSY COVER LEFT_UPPER	[illegible]	1			
27	HPA20_P_2ND	[illegible]	1			

NO.	PART NAME	PART NUMBER	QTY	MATERIAL	FINISHED	REMARK	
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							

DESIGNED	CHECKED	APPROVED	MODEL NAME	HPA20	SHEETS
DIM KEY			PART NUMBER	42-00563	1 / 1
HUMAX			PART NAME	HPA20_P2	

複製禁止