



2. ASSEMBLY DRAWING

2.1 Top View

2.1.1 ASIC (U1) correct orientation – **SMT-QC-01**

2.1.2 No cold solder joints (all components) – **SMT-QC-02**

2.1.3 Sufficient solder paste to form good joints (all components) – **SMT-QC-03**

